

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037711 FLE		
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (316) 269-7400			Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name			U.S. EPA ID Number				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Wichita, KS 67219 Facility's Phone: (316) 238-4012			U.S. EPA ID Number NE0981723513				
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) 1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S. (TOLUENE, LEAD), 9, PG III		10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes D004 D005 D007 D008 D039 D040
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information 1. CH881505X08 ENG#171 TRUCK # CHMT # 25126							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offeror's Printed/Typed Name				Signature		Month Day Year	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Signature Month Day Year Kendrick Shon/er 2/10/15 Transporter 2 Printed/Typed Name Signature Month Day Year							
18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____ 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: _____ 18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H040 2. 3. 4.							
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature Month Day Year							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037711 FLE				
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (316) 269-7400			Generator's Site Address (if different than mailing address) SAME						
6. Transporter 1 Company Name CLEAN HARBOR'S ENV			U.S. EPA ID Number MAD0393222250						
7. Transporter 2 Company Name			U.S. EPA ID Number						
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Bismarck, NE 68108 Facility's Phone: (408) 235-4012			U.S. EPA ID Number NED981723513						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
			No.	Type					
	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III		1	CM	EST 12	Y	D004	D005	D007
							D008	D039	D040
14. Special Handling Instructions and Additional Information 1. CH831506X0B ERG#171 TRUCK# CHRT# CHRT# 25126									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Officer's Printed/Typed Name JIM TYSON			Signature [Signature]			Month Day Year 12 10 15			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____									
17. Transporter Acknowledgment of Receipt of Materials			Signature Rinnie Stanley			Month Day Year 12 10 15			
Transporter 1 Printed/Typed Name			Signature			Month Day Year			
Transporter 2 Printed/Typed Name			Signature			Month Day Year			
18. Discrepancy									
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
Manifest Reference Number:									
18b. Alternate Facility (or Generator)						U.S. EPA ID Number			
Facility's Phone:									
18c. Signature of Alternate Facility (or Generator)						Month Day Year			
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H040		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name Thomas Clark			Signature [Signature]			Month Day Year 02 11 15			

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037711 FLE	
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (316) 269-7400			Generator's Site Address (if different than mailing address) SAME			
6. Transporter 1 Company Name CLEAN HARBORS ENV			U.S. EPA ID Number IND009322220			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Wichita, KS 67220 Facility's Phone: (316) 235-4012			U.S. EPA ID Number NED981723513			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
x	1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III	1. 12		12	Y	D004 D005 D007 D008 D039 D040
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information 1. CH831506X08 ERG#171 TRUCKS CHRT# CHRT# 25126						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name JOHN IVSON		Signature <i>[Signature]</i>		Month Day Year 2 10 15		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Rinnie Stanley		Signature <i>[Signature]</i>		Month Day Year 2 10 15		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____						
18b. Alternate Facility (or Generator) U.S. EPA ID Number						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H040		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Thomas Clark		Signature <i>[Signature]</i>		Month Day Year 2 11 15		



2247 South Highway 71
Kimball, NE 69145

TEL 308-235-4012
FAX 308-235-4307
www.cleanharbors.com

DATE: 2/11/2015

MANIFEST: 008037711FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department